

knitter-switch

Product Discontinuation Information

Product affected: LD 96 R

Effective date: immediately

Details:

With this component occur problems with suppliers which lead to excessive delivery delay.

Therefore we stopped production.

We recommend the following part instead:

LD 96 R 2

knitter-switch, September 2015



Oliver Kluj

Technical director