

# knitter-switch

## Discontinuation of Products

Products affected: MSP 101 C pushbutton-switch


Effectivity date: June 30, 2018

### Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, MPM 1 F is recommended.

knitter-switch, May 2018



Oliver Kluj

Technical Director