

# knitter-switch

## Discontinuation of Products

Products affected:                   MSP 121 B-SW, MSP 121 B RT pushbutton switches


Effectivity date:                    June 30, 2018

### Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, MPS 29 B-K and MPS 29 B-R are recommended.

knitter-switch, May 2018



Oliver Kluj

Technical Director