

Product Change Notification

Products affected: DRS 3116, DRS 4116
DRR 3116, DRR 4116
SMR 5116, SMR 5116 T

Effective date: from next production lot

Details:

The delivery position of the rotor will be changed from "0" to "F".

This measure improves the stability against soldering heat influence.

knitter-switch, November 2011



Oliver Kluj
Technical Director