

# knitter-switch

## Discontinuation of Products

Products affected: MFP 191 D-O slide-switch

Effectivity date: immediately

### Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, MFS 121 D-N is recommended.

knitter-switch, July 2018



Oliver Kluj

Technical Director