

knitter-switch

Discontinuation of Products

Products affected: MFP 191 D slide-switch

Effectivity date: after current stock is sold out

Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, MFP 12504 is recommended.

knitter-switch, September 2018



Oliver Kluj

Technical Director