

knitter-switch

Discontinuation of Products

Products affected: GFP 215 base plate for slide-switch

Effectivity date: immediately

Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

knitter-switch, May 2018



Oliver Kluj

Technical Director