

Discontinuation of Products

Products affected: LD 53, LD 53 S, LD 532

Effective date: immediately

Details:

The LED LD 531, used in LD 53 and LD 53 S, was discontinued by manufacturer, as well as the model LD 532, as alternative part, by other manufacturer.

Considerable efforts are being made to find another source of a matching LED – without success.

That was why we feel compelled to discontinue these products.

knitter-switch, June 2010



Oliver Kluj
Technical Director