

knitter-switch

Discontinuation of Products

Products affected: LD 30, LD 30S, LD 30S-24, LD 30-24
LD 32, LD 32S, LD 32S-24, LD 32-24
LD 40, LD 40S, LD 40S-24, LD 40-24
LD 42, LD 42S, LD 42S-24, LD 42-24
LD 60, LD 60S, LD 60S-24, LD 60-24
LD 62, LD 62S, LD 62S-24, LD 62-24


Effectivity date: after stock is sold

Details:

Tools are broken. Due to lack of demand, a renewal becomes uneconomical.

Please ask our sales staff for substitution models.

knitter-switch, December 2019



Oliver Kluj

Technical Director