

# knitter-switch

## Product Discontinuation Information

Product affected:

LD 32 S-12, LD 32 S-5, LD 32 SD, LD 32-12  
LD 34, LD 34 S  
LD 36, LD 36 S, LD 36 S-24, LD 36-24  
LD 42 SD, LD 42-12  
LD 44, LD 44 S  
LD 46, LD 46 S, LD 46 S-24, LD 46-24  
LD 56, LD 56 S  
LD 60-12  
LD 62 S-12, LD 62 SD, LD 62-12, LD 62-5  
LD 64, LD 64 S  
LD 66, LD 66 S, LD 66 S-24, LD 66-12, LD 6-24  
LDE 36, LDE 36 S, LDE 36 S W-24, LDE 36 S-12, LDE 36 S-24  
LDE 36 W, LDE 36 W-24, LDE 36-12, LDE 36-24  
LDE 46 N, LDE 46 S N, LDE 46 S W-24, LDE 46 S-12  
LDE 46 S-24 N, LDE 46 W, LDE 46 W-24, LDE 46-24 N  
LDE 56  
LDE 66, LDE 66 S, LDE 66 S W-24, LDE 66 S-24, LDE 66 W, LDE 66 W-24, LDE 66-24  
LDE 96 SR

Effective date: after current stock is sold out

Details:

Semiconductors needed for these products are no longer available, therefore we stopped production.

knitter-switch, November 2020



Oliver Kluj

Technical director