

# knitter-switch

## Discontinuation of Products

Products affected: LP 1 S-16G-202, LP 1 S-16G-209, LP 1 S-16G-809

LP 1 W-16G-202, LP 1 W-16G-809

LP2 S-16G-229, LP 2 S-16G-559, LP 2 S-16G-889

LP 2 S-16G-K, LP2S-16G-W-Z

LP 2 S-17G-229, LP 2 S-17G-559

Effectivity date: after stock is sold

### Details:

Tools for these products are worn out. Due to lack of demand, renovation of tools is uneconomic.

Please ask our sales staff for substitution models.

knitter-switch, August 2021



Oliver Kluj

Technical Director