

knitter-switch

Discontinuation of Products

Products affected: LP 2 SRR-PC, LP 2 SRG-PC, LP 2 SRY-PC
LP 2 SNR-PC, LP 2 SNG-PC, LP 2 SNY-PC
LP 2 SRR, LP 2 SRG, LP 2 SRY
LP 2 SNR, LP 2 SNG, LP 2 SNY
LP 2 WRR-PC, LP 2 WRG-PC, LP 2 WRY-PC
LP 2 WNR-PC, LP 2 WNG-PC, LP 2 WNY-PC
LP 2 WRR, LP 2 WRG, LP 2 WRY
LP 2 WNR, LP 2 WNG, LP 2 WNY

LP 2 S-26S-K, LP 2 S RY-C, LP 2 W-16S-809, LP 2 W NRG
LP 2 W NRG-PC, LP 2 W NYY-PC, LP 2 WRRG
LP 2 WRRG-PC

LP 1 S-17S-559, LP 1 S-17S-888, LP 1 SDG-PC
LP 1 SDR-PC, LP 1 SDY-PC, LP 1 SFG-PC, LP 1 SFR-PC
LP 1 S FYC-PC, LP 1 SFY-PC, LP 1 W FYC-PC


Effectivity date: after stock is sold

Details:

These products use Cadmium in contacts and will no longer be RohS-compliant after expiration of exemption in July 2021. Due to lack of demand, a redesign becomes uneconomical.

Please ask our sales staff for substitution models.

knitter-switch, November 2019



Oliver Kluj

Technical Director