

knitter-switch

Discontinuation of Products

Products affected: MFP 121 D RA-GN slide-switch


Effectivity date: immediately

Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, MFP 121 D-RA is recommended.

knitter-switch, May 2018



Oliver Kluj

Technical Director