

knitter-switch

Discontinuation of Products

Products affected: MFP 1420 slide-switch


Effectivity date: June 30, 2018

Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, MFP 140 is recommended.

knitter-switch, April 2018



Oliver Kluj

Technical Director