

knitter-switch

Discontinuation of Products

Products affected: MFP 150 R, MFP 150 RB slide-switches


Effectivity date: December 31, 2018

Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, MFP 150 and MFP 150 B are recommended.

knitter-switch, August 2018



Oliver Kluj

Technical Director