

knitter-switch

Discontinuation of Products

Products affected: MFP 1520 slide-switch


Effectivity date: June 30, 2018

Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, MFP 150 is recommended.

knitter-switch, May 2018



Oliver Kluj

Technical Director