

knitter-switch

Discontinuation of Products

Products affected: MFP 2520-10, MFP 2520-12 slide-switches


Effectivity date: June 30, 2018

Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, MFP 2520 is recommended.

knitter-switch, May 2018



Oliver Kluj

Technical Director