

# knitter-switch

## Discontinuation of Products

Products affected: MFS 201 N4 SW slide-switch


Effectivity date: December 31, 2018

### Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, MFS 201 N SW is recommended.

knitter-switch, August 2018



Oliver Kluj

Technical Director