

knitter-switch

Product-Discontinuation Notice

Affected products: MRK 1012 A, MRK 1012 A-R
MRK 1012 B, MRK 1012 B-R
MRK 1022 B, MRK 1022 B-R
MRK 1031 D, MRK 1031 D-R
MRK 1031 K-R, MRK 1031 L
MRK 1031 L-R, MRK 1343
MRK 2012 A

Effective date: immediately

Details:

Due to problems with components supplied by sub-contractors the production of these switch models stopped.

There is no drop-in replacement, please ask sales person in charge for suggestion.

knitter-switch, August 2021



Oliver Kluj

Technical Director