

knitter-switch

Product-Discontinuation Notice

Affected products: MRK 1041 L, MRK 1041 L-R


Effective date: immediately

Details:

Due to problems with components supplied by sub-contractors the production of these switch models stopped.

There is no drop-in replacement, please ask sales person in charge for suggestion.

knitter-switch, March 2020



Oliver Kluj

Technical Director