

# knitter-switch

## Product-Discontinuation Notice

Affected products: MRKC 1041 L


Effective date: immediately

### Details:

Due to problems with components supplied by sub-contractors the production of this switch model stopped.

There is no drop-in replacement, please ask sales person in charge for suggestion.

knitter-switch, August 2021



Oliver Kluj

Technical Director