

## Discontinuation of Products

Products affected: MSP 103 xx, see following page

Effectivity date: after current stock is sold


### Details:

Due to decreasing demand the production of these parts is discontinued.

We strongly recommend not to use these parts for new designs.

Please contact our local sales in case of ongoing demand.

knitter-switch, August 2022



Oliver Kluj

Technical Director

# knitter-switch

MSP 103 B	Pushbutton switch
MSP 103 B GK	Pushbutton switch
MSP 103 BK	Pushbutton switch
MSP 103 BK + KM409	Pushbutton Switch
MSP 103 C	Pushbutton switch
MSP 103 C-GK	Pushbutton switch
MSP 103 CK	Pushbutton switch
MSP 103 CK + KM409	Pushbutton Switch