

knitter-switch

Product-Discontinuation Notice

Affected products: TM 3 LG, TM 3 LR, TM 3 LY, TM 3 LYG
TR 3 LG, TR 3 LR, TR 3 LY

Effective date: immediately

Details:

Due to problems with components supplied by sub-contractors the production of these switch models stopped.

There is no drop-in replacement, please ask sales person in charge for suggestion.

knitter-switch, August 2021



Oliver Kluj

Technical Director