

knitter-switch

Product-Discontinuation Notice

Affected products: TSE 8 S, TSE 8 S-1, TSSE 8 S

Effective date: after current stock is sold out

Details:

Due to problems with components supplied by sub-contractors the production of these switch models stopped.

For replacement we recommend TSE 808-300, TSE 808-300-1, TSSE 808-300 which come with same PCB-layout, similar dimensions, increased number of cycles (from 1 Mio to 5 Mio cycles) and a proven sealing level of IP 67.

knitter-switch, October 2020



Oliver Kluj

Technical Director