

knitter-switch

Discontinuation of Products


Products affected: DSS 302, DSS 304, DSS 306, DSS 308, DSS 310
DSS 402, DSS 403, DSS 404, DSS 405, DSS 406
DSS 407, DSS 408, DSS 410

Effectivity date: After current stock is sold out

Details:

Due to lack of demand manufacturing of these parts was discontinued.
For replacement we suggest DSS 102 N to DSS 110 N.

knitter-switch, December 2014



Oliver Kluj

Technical Director