

knitter-switch

Discontinuation of Products

Products affected: DTS 010

Effectivity date: immediately

Details:

Due to lack of demand this detect-switch is discontinued.
DTS 010-1 is available as successor.

knitter-switch, November 2011



Oliver Kluj

Technical Director