

knitter-switch

Discontinuation of Products

Products affected: MFP 101 D-RA slide switch


Effectivity date: immediately

Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, MFP 120 R is recommended.

knitter-switch, February 2018



Oliver Kluj

Technical Director