

knitter-switch

Discontinuation of Products

Products affected: MFP 1420 R, MFP 1520 R, MFP 1620 R slide switches


Effectivity date: immediately

Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, MFP 140 R, MFP 2520, MFP 1620 are recommended.

knitter-switch, February 2018



Oliver Kluj

Technical Director