

knitter-switch

Discontinuation of Products

Products affected: MFP 263 P slide-switch

Effectivity date: immediately

Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, MFP 213 P, MFP 223 P and MFP 2323 are recommended.

knitter-switch, February 2012



Oliver Kluj

Technical Director