

knitter-switch


Product-Change Notice P2021-12

Products affected: DBS 3001, DBS 3002, DBS 3002-VM, DBS 3003, DBS 3003-VM
DBS 3004, DBS 3004-VM, DBS 3005, DBS 3005-VM, DBS 3006
DBS 3006-VM, DB 3007, DBS 3007-VM; DBS 3008, DBS 3008-VM
DBS 3009, DBS 3009-VM, DBS 3010, DBS 3010-VM, DBS 3012
DBS 3012-VM
DBS 3101, DBS 3101 SL, DBS 3102, DBS 3102 B, DBS 3102-VM
DBS 3103, DBS 3103-VM, DBS 3104, DBS 3104 B, DBS 3104-SL
DBS 3104 THR, DBS 3104-VM, DBS 3105, DBS 3105-VM
DBS 3106, DBS 3106 B, DBS 3106-SL, DBS 3106-VM, DBS 3107
DBS 3107 B, DBS 3107-VM; DBS 3108, DBS 3108 SL, DBS 3108-VM
DBS 3109, DBS 3109-VM, DBS 3110, DBS 3110 B, DBS 3110-VM
DBS 3112, DBS 3112-VM

Effective date: from September 2021 production

Details:


For reasons of environmental protection and production speed the marking of the housings changes from pad print to laser print. There are no further changes on product and packing.



pad print

laser print

Knitter-switch, September 2021



Oliver Kluj
Technical Director