

Discontinuation of Products

Products affected: MRP 1-20, MRP 1-20-1, MRP 1-20 R, RR 775

Effectivity date: after current stock is sold


Details:

Due to decreasing demand the production of these parts is discontinued.

We strongly recommend not to use these parts for new designs.

Please contact our local sales in case of ongoing demand.

knitter-switch, February 2025



Oliver Kluj

Switches