

Discontinuation of Products

Products affected: D 102 H, D 103 H, D 104 H, D 105 H, D 106 H, D 107 H,
D 108 H, D 110 H

Effective date: after current stock is sold out

Details:

Owing to a lack of demand the components are discontinued.

These types are optional accessory to the DIL-switches DSS 100, DSS 200, DSS 300, DSS 400.

Due to the redesign or replacement of this switch-series by DSS 100 N, DSS 200 N, DSS 300 N, DSS 400 N, these products don't fit no longer.

knitter-switch, December 2009



Oliver Kluj
Technical Director