

Discontinuation of Products

Products affected: DSS 101 N, DSS 102 N, DSS 103 N, DSS 104 N, DSS 105 N
DSS 106 N, DSS 107 N, DSS 108 N, DSS 110 N

Effectivity date: after current stock is sold

Details:

Due to decreasing demand the production of these DIL-switches is discontinued.

For replacement we suggest our professional series DSS 201 N, DSS 202 N, etc.

Apart from Gold plating layer thickness and electrical life, DSS 100 N and DSS 200 N are same.

Surface layer thicknesses:

DSS 100 N: 1.25 μm Gold over 1 μm Nickel


DSS 200 N: 0.2 μm Gold over 1 μm Nickel

Life:

DSS 100 N: mechanical/electrical: 10 000 cycles

DSS 200 N: mechanical: 10 000 cycles, electrical 5 000 cycles

knitter-switch, August 2022



Oliver Kluj

Technical Director