

knitter-switch

Discontinuation of Products

Products affected: MFP 201 N-RT, MFP 201 N-SW
MFP 201 N RA-RT, MFP 201 N RA-SW

Effectivity date: After current stock is sold out

Details:

Due to lack of demand production is discontinued.

For replacement consider use of MFP 201 N and MFP 201 N-RA, which has a black slider.

knitter-switch, August 2018



Oliver Kluj

Technical Director