

knitter-switch

Discontinuation of Products

Products affected: MSS 101 DB, MSS 111 DB, MSS 201 NB

Effectivity date: After current stock is sold out

Details:

Due to lack of demand production of these slide switches was discontinued.

Our sales will suggest alternative parts if required.

knitter-switch, April 2011



Oliver Kluj

Technical Director