

knitter-switch

Product Change Notice P02-2025


Products affected: DBP 8002, DBP 8004, DBP 8006, DBP 8008, DBP 8010, DBP 8102, DBP 8102 H, DBP 8104, DBP 8106, DBP 8108, DBP 8110, DBP 8202, DBP 8206, DBP 8208, DBP 8302, DBP 8304, DBP 8308

Effectivity date: after current stock is sold

Details:

In course of move from manual to automatic assembling a design improvement and the change from pad- to laser-print will be introduced.

There are no relevant changes in dimensions and specification, data-sheets are still valid.



knitter-switch - Baldham, May 2025

Oliver Kluj
Switches