

knitter-switch

Product Change Notice P04-2025

Products affected: DPW/DPWL series, details see page 2

Effectivity date: 30.11.2025


Details:

In course of continuously product improvement the manufacturing process of the switching element inside the bushing has been optimized.


The changes comprise:

The bushing design has been modified to eliminate the cutout for the fixing pin


Current:



New:



knitter-switch - Baldham, November 2025



Oliver Kluj
Switches

knitter-switch

Parts list

DPW 1 CG B-FO	DPWL 1 CG S-GB	DPWL 1 CG-BW
DPW 1 CG D1-K-PC	DPWL 1 CG S-GG	DPWL 1 CG-BY
DPW 1 CG O-FO	DPWL 1 CG S-GR	DPWL 1 CG-GB
DPW 1 CG SB-FO	DPWL 1 CG S-GW	DPWL 1 CG-GW
DPW 1 CG SG-FO	DPWL 1 CG S-GY	DPWL 1 CG-GY
DPW 1 CG SK-FO	DPWL 1 CG S-KB	DPWL 1 CG-KR
DPW 1 CG SO-FO	DPWL 1 CG S-KG	DPWL 1 CG-KRG-L042
DPW 1 CG SR-FO	DPWL 1 CG S-KR	DPWL 1 CG-KW
DPW 1 CG SW-FO	DPWL 1 CG S-KW	DPWL 1 CG-KY
DPW 1 CG SY-FO	DPWL 1 CG S-KY	DPWL 1 CG-OG
DPW 1 CG Y-FO	DPWL 1 CG S-OB	DPWL 1 CG-OR
DPW 1 CG-G	DPWL 1 CG S-OG	DPWL 1 CG-OW
DPW 1 CG-K	DPWL 1 CG S-OR	DPWL 1 CG-OY
DPW 1 CG-K-NH	DPWL 1 CG S-OW	DPWL 1 CG-RB
DPW 1 CG-K-WW	DPWL 1 CG S-OY	DPWL 1 CG-RG
DPW 1 CG-O	DPWL 1 CG S-RB	DPWL 1 CG-RR
DPW 1 CG-R-A	DPWL 1 CG S-RG	DPWL 1 CG-RW
DPW 1 CG-S-B	DPWL 1 CG S-RR	DPWL 1 CG-RY
DPW 1 CG-S-G	DPWL 1 CG S-RW	DPWL 1 CGS-K-R-KNE02
DPW 1 CG-S-K	DPWL 1 CG S-RY	DPWL 1 CGS-K-R-KNE03
DPW 1 CG-S-O	DPWL 1 CG S-WB	DPWL 1 CG-WB
DPW 1 CG-S-R	DPWL 1 CG S-WG	DPWL 1 CG-WG
DPW 1 CG-S-W	DPWL 1 CG S-WR	DPWL 1 CG-WR
DPW 1 CG-S-Y	DPWL 1 CG S-WW	DPWL 1 CG-WW
DPW 1 CG-W-WW	DPWL 1 CG S-WY	DPWL 1 CG-WY
DPW 1 CG-Y-WW	DPWL 1 CG S-YB	DPWL 1 CG-YB
DPW 11 CG-S-O-41M2	DPWL 1 CG S-YG	DPWL 1 CG-YG
DPWL 1 CG S-BB	DPWL 1 CG S-YR	DPWL 1 CG-YR
DPWL 1 CG S-BG	DPWL 1 CG S-YW	DPWL 1 CG-YW
DPWL 1 CG S-BR	DPWL 1 CG S-YY	DPWL 1 CG-YY
DPWL 1 CG S-BW	DPWL 1 CG-BG	DPWL1CGKW-SD2I
DPWL 1 CG S-BY	DPWL 1 CG-BR	DPWL1CGRW-SD2I